





Montageanleitung / Mounting Instruction




1 x 1 x








2 x 2 x






4 x 8
4 x 10
4 x 12 2 x

PZ 2
2 Nm

		
t = 5	l = 8	c = 1 x 45°
t = 6	l = 10	c = 2 x 45°
t = 7	l = 10	c = 3 x 45°
t = 8	l = 12	c = 4 x 45°